

Noise Levels at LT-1
~ 420 feet from Center of Columbus Parkway, East of Turnberry Way Residences
Thursday, April 29, 2010





Figure 2

Noise Levels at LT-1
~ 420 feet from Center of Columbus Parkway, East of Turnberry Way Residences
Friday, April 30, 2010



4.12-3

Noise Levels at LT-1
~ 420 feet from Center of Columbus Parkway, East of Turnberry Way Residences
Saturday, May 1, 2010





Figure 4


Noise Levels at LT-1
~ 420 feet from Center of Columbus Parkway, East of Turnberry Way Residences
Sunday, May 2, 2010



58 dBA Ldn

Figure 5

Noise Levels at LT-1
~ 420 feet from Center of Columbus Parkway, East of Turnberry Way Residences
Monday, May 3, 2010



59 dBA Ldn

Figure 6

Noise Levels at LT-1
~ 420 feet from Center of Columbus Parkway, East of Turnberry Way Residences
Tuesday, May 4, 2010




Figure 7

Noise Levels at LT-2
~ Sky Valley Lane, East of Lake Herman Quarry
Thursday, April 29, 2010




Figure 8

Noise Levels at LT-2
~ Sky Valley Lane, East of Lake Herman Quarry
Friday, April 30, 2010




Figure 9

Noise Levels at LT-2
~ Sky Valley Lane, East of Lake Herman Quarry
Saturday, May 1, 2010




Figure 10

Noise Levels at LT-2
~ Sky Valley Lane, East of Lake Herman Quarry
Sunday, May 2, 2010




Figure 11

**Noise Levels at LT-2
~ Sky Valley Lane, East of Lake Herman Quarry
Monday, May 3, 2010**




Figure 12

Noise Levels at LT-2
~ Sky Valley Lane, East of Lake Herman Quarry
Tuesday, May 4, 2010




Figure 13

Noise Levels at LT-3
~ Lake Herman Quarry near Asphalt/Concrete Plants
Thursday, April 29, 2010




Figure 14

**Noise Levels at LT-3
~ Lake Herman Quarry near Asphalt/Concrete Plants
Friday, April 30, 2010**





Figure 15

**Noise Levels at LT-3
~ Lake Herman Quarry near Asphalt/Concrete Plants
Saturday, May 1, 2010**



56 dBA Ldn

Figure 16

Noise Levels at LT-3
~ Lake Herman Quarry near Asphalt/Concrete Plants
Sunday, May 2, 2010




Figure 17

**Noise Levels at LT-3
~ Lake Herman Quarry near Asphalt/Concrete Plants
Monday, May 3, 2010**




Figure 18

**Noise Levels at LT-3
~ Lake Herman Quarry near Asphalt/Concrete Plants
Tuesday, May 4, 2010**




Figure 19

**Noise Levels at LT-4
~ End of St. John's Mine Road at McIntire Ranch
Thursday, April 29, 2010**




Figure 20

**Noise Levels at LT-4
~ End of St. John's Mine Road at McIntire Ranch
Friday, April 30, 2010**




Figure 21

**Noise Levels at LT-4
~ End of St. John's Mine Road at McIntire Ranch
Saturday, May 1, 2010**




Figure 22

**Noise Levels at LT-4
~ End of St. John's Mine Road at McIntire Ranch
Sunday, May 2, 2010**




Figure 23

**Noise Levels at LT-4
~ End of St. John's Mine Road at McIntire Ranch
Monday, May 3, 2010**




Figure 24

**Noise Levels at LT-4
~ End of St. John's Mine Road at McIntire Ranch
Tuesday, May 4, 2010**




Figure 25