



**Noise Levels at LT-1**  
**~ 420 feet from Center of Columbus Parkway, East of Turnberry Way Residences**  
**Thursday, April 29, 2010**




**Figure 2**

**Noise Levels at LT-1**  
**~ 420 feet from Center of Columbus Parkway, East of Turnberry Way Residences**  
**Friday, April 30, 2010**




4.12-3

**Noise Levels at LT-1**  
**~ 420 feet from Center of Columbus Parkway, East of Turnberry Way Residences**  
**Saturday, May 1, 2010**



**Figure 4**


**Noise Levels at LT-1**  
**~ 420 feet from Center of Columbus Parkway, East of Turnberry Way Residences**  
**Sunday, May 2, 2010**



58 dBA Ldn

**Figure 5**


**Noise Levels at LT-1**  
**~ 420 feet from Center of Columbus Parkway, East of Turnberry Way Residences**  
**Monday, May 3, 2010**



59 dBA Ldn


**Figure 6**

**Noise Levels at LT-1**  
**~ 420 feet from Center of Columbus Parkway, East of Turnberry Way Residences**  
**Tuesday, May 4, 2010**




**Figure 7**

**Noise Levels at LT-2**  
**~ Sky Valley Lane, East of Lake Herman Quarry**  
**Thursday, April 29, 2010**



**Figure 8**


**Noise Levels at LT-2**  
**~ Sky Valley Lane, East of Lake Herman Quarry**  
**Friday, April 30, 2010**



**Figure 9**




**Noise Levels at LT-2**  
**~ Sky Valley Lane, East of Lake Herman Quarry**  
**Saturday, May 1, 2010**




**Figure 10**

**Noise Levels at LT-2**  
**~ Sky Valley Lane, East of Lake Herman Quarry**  
**Sunday, May 2, 2010**




**Figure 11**

**Noise Levels at LT-2**  
**~ Sky Valley Lane, East of Lake Herman Quarry**  
**Monday, May 3, 2010**




**Figure 12**

**Noise Levels at LT-2**  
**~ Sky Valley Lane, East of Lake Herman Quarry**  
**Tuesday, May 4, 2010**




**Figure 13**

**Noise Levels at LT-3**  
**~ Lake Herman Quarry near Asphalt/Concrete Plants**  
**Thursday, April 29, 2010**




**Figure 14**

**Noise Levels at LT-3  
~ Lake Herman Quarry near Asphalt/Concrete Plants  
Friday, April 30, 2010**




**Figure 15**

**Noise Levels at LT-3  
~ Lake Herman Quarry near Asphalt/Concrete Plants  
Saturday, May 1, 2010**



**Figure 16**


**Noise Levels at LT-3  
~ Lake Herman Quarry near Asphalt/Concrete Plants  
Sunday, May 2, 2010**



**Figure 17**




**Noise Levels at LT-3  
~ Lake Herman Quarry near Asphalt/Concrete Plants  
Monday, May 3, 2010**




**Figure 18**

**Noise Levels at LT-3  
~ Lake Herman Quarry near Asphalt/Concrete Plants  
Tuesday, May 4, 2010**




**Figure 19**

**Noise Levels at LT-4  
~ End of St. John's Mine Road at McIntire Ranch  
Thursday, April 29, 2010**




**Figure 20**

**Noise Levels at LT-4  
~ End of St. John's Mine Road at McIntire Ranch  
Friday, April 30, 2010**




**Figure 21**

**Noise Levels at LT-4  
~ End of St. John's Mine Road at McIntire Ranch  
Saturday, May 1, 2010**




**Figure 22**

**Noise Levels at LT-4  
~ End of St. John's Mine Road at McIntire Ranch  
Sunday, May 2, 2010**




**Figure 23**

**Noise Levels at LT-4  
~ End of St. John's Mine Road at McIntire Ranch  
Monday, May 3, 2010**



**Figure 24**

**Noise Levels at LT-4  
~ End of St. John's Mine Road at McIntire Ranch  
Tuesday, May 4, 2010**



**Figure 25**